


Original Design, Idler Housing and DI Supply to Mandrels/PVA Issues with Original Design during Scrubber Operation



THE INVENTION

